Evening and overnight closures along the A38 in **Derbyshire next week**

The works aim to make the road's LED lighting more energy efficient and require less maintenance in the future

SHARE

 \mathbb{X}



By Carrington Walker 04:00, 9 FEB 2025

Bookmark





Roads closures are set to be put in place for drivers travelling along the A38, between Toyota Island and Little Eaton, as further works are carried out on the road's new LED lighting.

Get the latest Derbyshire Live breaking news on WhatsApp

Our community members are treated to special offers, promotions and adverts from us and our partners. You can check out at any time. More info

09/02/2025, 10:20

(S) Join us on WhatsApp

Part of the A38 in Derbyshire will be undergoing evening and overnight closures next week. Motorists travelling along the A38, between Toyota Island and Little Eaton, have been warned of further works carried out on the road's new LED lighting.

From Monday (February 10), work will be carried out on weeknights between 8pm to 6am - predominantly under slip road and lane closures, with some full carriageway closures along the stretch.

National Highways said that every effort would be made "to ensure the impact on the local community and travelling public is kept to a minimum". Access for emergency service vehicles will be maintained throughout.

For the next two weeks, until February 20, evening and overnight closures will be in place across the following sections due to the repair scheme:

- 10 February Findern Interchange to A516 Mickleover junction full northbound carriageway closure
- 11 February to 13 February A516 eastbound to A38 northbound link road closure
- 14 February to 17 February A38 southbound to A516 westbound link road closure
- 18 February to 19 February Northbound exit slip road to Hospital Island
- 20 February Southbound entry slip road from Hospital Island


Diversion routes with full signage will be in place for drivers to follow, pictured below.

2 of 4 09/02/2025, 10:20

link road Findern Interchange to A516 Mickleover

Diversion for A38 southbound to A516 westbound link road from B to A

Diversion for A516 eastbound to A38 northbound




The Findern Interchange to A516 Mickleover junction full northbound carriageway, A516 eastbound to A38 northbound link road and A38 southbound to A516 westbound link road diversions. (Image: Google)

The A38 Claymills to Branston southbound route will also undergo a full closure for essential maintenance on Monday (February 10) from 9pm to 6am. The work will include drainage gully work and patches of resurfacing along the route.

Northbound exit slip road to Hospital Island diversion

Southbound entry slip road from **Hospital Island**



🗖 The Northbound exit slip road to Hospital Island and Southbound entry slip road from Hospital Island diversions. (Image: Google)

Again, a fully signed diversion route will be in place that will take drivers off the A38 southbound at the Claymills junction, along the A5121 through Burton upon Trent, to rejoin the A38 at the Branston junction.

09/02/2025, 10:20 3 of 4